



# professional

## Multi-V Belts

fits

Renault 1.4 16V (K4J) and 1.6 16V (K4M)  
Engines with air conditioning systems



### PROBLEM

The v-ribbed belt is noisy, wears quickly and may tear.

### CAUSE

The original version of the v-ribbed belt has 6 ribs. Using the 6-ribbed belt may lead to the belt flank wearing faster and ribs being ripped out (see Fig. 1). The result may be major engine damage.

### SOLUTION

Renault has adjusted the belt. SWAG recommends using SWAG belt 10 92 8885 (repl. no. 77 00 111 671). The new version has 5 ribs while all belt pulleys have 6 grooves. This prevents faster wear and premature tearing. The new version also reduces noise and achieves a longer belt life.

### NOTE ON FITTING

Please note that the belt must be placed onto the grooves such that the inner groove remains free on all belt pulleys (see Fig. 2).

### PLEASE NOTE

Please also make sure to check that the freewheeling alternator pulley is working perfectly before replacing the belt.



**SWAG no. 10 92 8885**  
repl. No. 77 00 111 671