

## Radiator fan runs continuously at maximum speed

Part Number: 696091

For vehicle: Peugeot 307 2000 >

The Valeo Service Technical department have received several claims stating that radiator fan 696091 continuously operates at maximum speed.

After investigating the issue Valeo technicians have identified that the cooling fan motor is not at fault. The fault is related to the **engine cooling fan control unit** which isn't regulating the speed of the motor.

If this occurs the radiator fan will not need replacing only the engine cooling fan control unit. (pictured below).

