

850792/850793 - Noise during operation

Part Number: 850792/850793

For Vehicle: Renault Clio 2005-2009

The Valeo Service Technical department have had several calls stating, that after fitting window regulator 850792 or 850793 there is noise heard during operation.

After investigating the issue, Valeo technicians have identified that the window regulator is not at fault. The issue is caused by excessive play between the bolts and mounting points. This excessive play manifests itself as a slight vibration/rattle.

In order to fix the issue, Valeo Service advise to remove the door panel and fit washers (OE Code: 77 03 053 951) to the mounting bolts as shown below (A). This should remove the excess movement and eliminate the noise.

