

Faulty release arm or guide sleeve

Part Number: 826362

For Vehicle: VW Polo 1.2 2005>

The Valeo Service Technical department have received several claims stating that after fitment of clutch kit 826362 there is an issue where the clutch pedal sits low or drops to the floor.

After further investigation Valeo technicians have identified that the clutch kit itself is not at fault and the symptoms seen is as a consequence of a worn release arm or guide sleeve.

To fix the issue Valeo Service advise to check the following:

- 1) While replacing the clutch check the release arm and the guide sleeve.
- 2) If there is any sign of them being worn or damaged replace either the release arm or the guide sleeve.
Valeo Service recommends replacing the guide tube with every clutch change.

Guide sleeve OE number 085141181 required.

