

Difficulty in changing third and fourth gear

Part Number: 835064

For Vehicle: Opel/Vauxhall Corsa 1.3d 2005>

The Valeo Service Technical department have received several claims stating that after fitment of the clutch kit 835064 there are difficulties with changing gears. The issue is when trying to engage third or fourth gears.

After investigating the issue Valeo technicians have identified that the clutch kit itself is not at fault. The actual cause is a worn or faulty third and fourth gear synchro hub ring thus creating poor engagement on the gears.

To fix the issue it is advised the following steps are completed:

- 1) Renew the third and fourth gear synchroniser ring.
- 2) Renew the third and fourth gearwheel.

Parts required:

Repair kit: (OE Code: 24579261)

Synchroniser: (OE Code: 98500183)

Bearing: (OE Code: 55564062)

Third gearwheel: (OE Code: 24579604)

Fourth gearwheel: (OE Code: 24579614)

Please note there is no need to change the clutch

