Release fork issues for Kia Sedona 2.9 TD

Part Number: 826406

For Vehicle: Kia Sedona 2.9 TD 1999 > 2006 with engine codes J3

The Valeo Service Technical department have received a number of calls and claims concerning clutch part number 826406 with end users stating that the clutch will not engage or it is difficult to select gears. After conducting in depth analysis it has been found that the clutch itself is not the cause of the issue but the release fork.

Before replacing the clutch kit please check the clutch release fork for stress fractures as this can affect the performance of the release mechanism. If stress fractures are found please replace the release fork. The O.E part number for the release fork is **OK71E-16-520**.



O.E Fork arm of OK71E-16-520



