

DPFE sensor and EGR valve for Ford Focus

Part Number: 700412

For Vehicle: Ford Focus/C max

The DPFE (Delta/Differential Pressure Feedback of EGR) sensor can sometimes fail and when this does so it can give the PCM (power train control module) incorrect information and more often than not the 'check engine light' will not come on until the DPFE sensor has completely malfunctioned.

Fault codes may be incorrectly displayed regarding an EGR valve malfunction. It is best practice to test the DPFE sensor before replacement of the EGR valve. It is recommended to change the DPFE sensor every 30,000 miles.



DPFE sensor



Valeo EGR valve 700412