

734333 – Damage on Radiator

Part Number: 734333

For Vehicle: Select VAG Models

The Valeo Service Technical department have had several claims stating that after fitment of radiator 734333, the vehicle can suffer from coolant loss and/or the coolant level warning light illuminates.

After investigating the issue Valeo technicians have identified that the likely cause is that the radiator has become damaged by a fitting clip on the cooling fan catching the radiator whilst in use.

To fix the issue, it is recommended to follow these steps:

- 1) Check the cooling system for leaks.
- 2) Remove the cooling fan housing.
- 3) Check the radiator for damage (Fig 1).

If damage is found:

- 1) Replace the radiator.
- 2) Check the cooling fan. Check the fan has the correct fitting (Fig 2).
- 3) The clip should sit flush with the bar, so there is no protrusion to catch the radiator (Fig 3).

