

Wiper Motor - Self Tapping Screws

Part Number: 404520, 579140, 579206, 579223, 579709, 579711, 579738, 579740, 579748, 579750, 579753, 579754

For Vehicle: Various

Valeo Service has received several calls through the Technical hotline, regarding the fixation holes on the above part numbers of wiper motors.

Please note that on those part numbers above, the fixation holes are manufactured with no thread as per Fig 1.

The units: 579206, 579223, 579709, 579748, 579750, 579753 & 579754 are all supplied with self tapping screws that thread the fixation holes when the screws are screwed into the unit as per Fig 2 and Fig 3.

Please use the screws supplied (on the units that come supplied with self-tapping screws) with the new unit and not the screws off the unit being replaced. For units that are not supplied with new screws, please check the thread is in good condition, if not new bolts will need to be supplied.

Fig 1



Fig 2



Fig 3

