



Various BMW & VAG Group Vehicles

CLTB 0020


Ball Race Release Bearings Which Appear To Have A Plastic Contact Face

Concerns; We have had several instances now of garages quering if the plastic face is just for protection and should it be removed proir to fitting

Method; Under no circumstances should this special plastic interface be removed, as it is a specific design feature of the clutch kit it is with.

WARNING

DO NOT REMOVE THIS PLASTIC INTERFACE



www.borgandbeck.com

TECHNICAL INFORMATION