




Moveable Release Bearing Face Various B.M.W. 1, 3 and 5 Series

CLTB 0019

Concerns; We have been receiving enquiries about the release bearings rotating clutch interface appearing to be loose/faulty.

(See photo below)



Moveable/Loose Bearing Face

Method; Please be aware that the front rotating clutch interface will appear to be loose, but this is perfectly acceptable as it is a design feature to improve release bearing performance.



www.borgandbeck.com

TECHNICAL INFORMATION