

Blue Print Top Tip

Chrysler PT Cruiser Thermostat Housing Replacement

Applicable References: **ADA109212**

Applications: Chrysler PT Cruiser 2.0i, 2.4i 2000>

Date Issued: 03/2011

The thermostat housing/coolant filler neck is a plastic moulded item (located towards the OSF of the engine compartment) that can often warp or crack from thermal expansion and contraction.

Replacement is the only option for a long-lasting repair, and it is considered good practice to renew the thermostat and gasket (**ADA109210C**) at the same time as there would be no additional labour involved.

No specialist tools are required for changing the thermostat or housing.

Unlike the main dealer, Blue Print offers a 3 Year unlimited mileage warranty on every part, meaning peace of mind for the vehicle owner knowing that they won't need to pay for the same repair anytime soon.

The Thermostat Housing is also referred to as -

- Filler Neck and Thermostat Housing
- Thermostat Housing Cover



ADA109212

Thermostat Housing



Also available...

ADA109210C

Thermostat



www.blue-print.com

Disclaimer : Any technical tips are produced in good faith. Automotive Distributors Ltd. always recommend that vehicle maintenance and diagnostics are only carried out by suitably experienced people using appropriate tools in a safe manner within a workshop environment. Automotive Distributors Ltd. and their customers cannot be held responsible for the correctness of, or misinterpretation of the above technical tips. Images shown are for illustrative purposes only and may not be representative of the products or vehicles described.