

# Technical Bulletin

Technical Helpline: +44(0)1622 833004 Fax: +44(0)1622 834004

## ADH28668 Upper Ball Joint

Date Issued: 01/08/2007

### Subject – Application Guide

#### Vehicle - Honda Accord 1990 > 1998

We have encountered several cases where the Upper Ball Joint part number ADH28668 will not fit some Honda Accord suspension arm applications.

ADH28668 has no OE equivalent part number, this part is manufactured solely for Blue Print and is not available to purchase from Honda.

If you wish to purchase a ball joint from a Honda dealer, you will have to purchase a complete suspension arm – Honda do not manufacture a replacement ball joint.

ADH28668 Ball Joint will only fit Honda OE suspension arms and Blue Print suspension arms (part numbers ADH28617 & ADH28618).

If the vehicle has had a suspension arm or arms changed using some other aftermarket parts, ADH28668 is unlikely to fit! You will need to replace the complete suspension arm.

#### Linked part numbers:

Left hand front upper suspension arm - ADH28617.

Right hand front upper suspension arm - ADH28618



**Disclaimer** : Any technical tips are produced in good faith. Blue Print, always recommend that vehicle maintenance and diagnostics are only carried out by suitably experienced people using appropriate tools in a safe manner within a workshop environment. Blue Print, and their customers cannot be held responsible for the correctness of, or misinterpretation of the above technical tips. Images shown are for illustrative purposes only and may not be representative of the products or vehicles described.



[www.blue-print.com](http://www.blue-print.com)