



## All Vehicles

Fitted with a Concentric Slave Cylinder (CSC)

CLTB 0012

# CONCENTRIC SLAVE CYLINDERS FITTED WITH A TRANSPORT CLIP

### Concerns

Concentric Slave Cylinders (CSCs) have been fitted and operated without removing the plastic transport clip.

In some cases, the transport clip has been removed prior to fitment leading to accidental dry compression as shown in CLTB0003.

### Method

Always use the supplied replacement sealing ring before tightening the CSC unit retaining bolts to 8-12Nm, then remove the plastic transport clip and refit the gearbox.

