

LINK ROD TIGHTENING ADVICE

FAI recommend that an airgun should not be used to tighten the nuts on a link rod.



Using an airgun increases the risk of

- Over tightening
- Snapped ball pin
- Cross threading shearing thread

FAI recommend that only a suitable manual tool should be used.





Gary Hammond

Senior Product Manager - Steering & Suspension

Tel: +44 (0) 8708 391883 Fax: +44 (0) 8708 391804

Email: gary.hammond@fai.co.uk

Web: www.faiauto.com

