



Alfa 166 2.4 JTD Radiator fan runs permanently

Due to a defect control relay the radiator fan permanently runs.

If the above mentioned fault occurs, although the ignition key is removed, the cause could be the control relay of the first fan stage. The contacts in the relay burn and weld together. In this case the control relay must be replaced (Fig 1).

After the exchange, check the function of the system. If the system still doesn't work faultlessly, the relay of the second fan stage must be replaced too. To change the second relay, the distributor box (in the left front partition panel) must be removed.



Bulletin