



1-1

© Hella KGaA Hueck & Co., Lippstadt

5. März 2004

BMW E36 All vehicles since start of series

Starter failure.

If there are complaints with these vehicles that the starter does not work, one possible cause could be a faulty ignition lock. After start-up, the faulty ignition lock sticks in the start position, thereby damaging the starter as well. To eliminate the fault, the complete ignition and steering lock and the starter have to be replaced.

Bulletin

