Bulletin



© Hella KGaA Hueck & Co., Lippstadt 24. April 2003 1-1

Fiat Punto build year 09.1999

Illumination of the control lamps after switching off the engine.

If, on this vehicle, the customer complains that the control lamps in the instrument cluster illuminates after switching off the engine and ignition, a possible cause could be a software mistake in the instrument cluster.

If this fault occurs, no parts must be renewed. To rectify the problem, only the battery must be disconnected for a short time.



Bulletin

