



Ford Galaxy Model year: up to July 1996 With automatic air conditioning

Faulty / no display of air-conditioning operating unit

With the above-mentioned vehicles, there can be problems with a fault display on or complete failure of the air-conditioning operating unit. Thus, for example, the display can flash in the "off" position or not show anything at all.

To remedy the problem, the fault memory should be read out first, and any faults indicated then eliminated. If this does not solve the problem, the fault must be assumed to be in the operating unit itself.

The operating unit should be removed as follows:

- Remove the radio (note code beforehand if necessary)
- Remove the radio plug
- Reach behind the air-conditioning operating unit
- Unlock the catch underneath the operating unit and use gentle pressure to pull the unit out forwards
- Remove the plug

From model year August 1996, modified operating units were installed in the factory.