Bulletin



Nissan Juke (F15) Model year: 2010 Vehicles with seat heating

Malfunctioning of the seat heating.

If complaints are made about the functioning of the seat heating in the above-mentioned vehicles, a faulty or defective wiring harness should be considered as a potential cause of the trouble.

The following vehicles can be affected: Production period from 16.08.2010 to 30.09.2010

The vehicle manufacturer has already taken up the problem and has notified the owners of the affected vehicles. Nevertheless, one may assume that for various reasons not all vehicles have been checked and repaired.

In the event of such malfunctioning, an adapter cable is available from the vehicle manufacturer.

Adapter cable: spare part (SP No.) 87019 1KL0A

Page 1 of 1

2015

© HELLA KGaA Hueck & Co., Lippstadt Reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and can not be used as a basis for installation or design. All rights reserved.

