



## **OPEL**

**Astra G, Vectra B, Omega B,**

**Frontera B, Sintra, Zafira**

**Model year: 1998 - 2000**

**Engine: X20DTL, X20DTH, X22DTH**

### **Problems with cold start**

At coolant temperatures between + 5°C and + 10°C, the above-mentioned vehicles could have start-up problems. The "efficiency" of the injection timing device no longer being sufficient must be considered as a possible cause of the problem. If other sources of fault can be excluded as the cause, a software update can often remedy the problem. Contact an authorized Opel garage concerning this matter.