BULLETIN



Opel Astra H From model year 2004 With dynamic bend lighting "Dynabeam"

Replacement of the light source

If the light source has to be replaced in the vehicle specified above, proceed as follows:

disassemble the front apron of the vehicle and remove the headlamp.

Then replace the light source, e.g., H7 as follows:

- remove the cover cap (Figure 1).
- disengage the light source holder (Figure 2).
- remove the defective light source from the connector and insert a light source that is intact (Figure 3).
- engage the light source holder (Figure 4).
- now carry out a function test.
- mount the cover cap (Figure 1).
- mount the headlamp and the front apron.
- adjust the headlamp using a beamsetter.



Figure 1



Figure 2



Figure 3



Figure 4

