



Bulletin

Opel Astra J Model year: 2010 onwards Radio: CD300 / CD400 / CDC400

Delayed warning and indicator tones. Delayed warning tones for the parking aid.

If it is reported that warning, indicator or parking aid tones are providing delayed notification for these vehicles, a deviation in the software should be considered as a potential cause.

Radio models affected with delayed tone playback for indicators and the parking aid: CD300; CD400; CDC400.

The vehicle manufacturer has already recognized the problem and has corrected it using a software update. It must be assumed, however, that for a variety of reasons not all vehicles have been checked or repaired.

Improved software has been in use at the vehicle manufacturer since August 2012.