



## **OPEL**

### **Corsa C**

### **Model year: 2001 - 2003**

### **Engine: CZ10XE + Z12XE**


### **With MTA gearbox**

### **Problems with OBD exhaust emissions**

With the above-mentioned vehicles, communication problems can occur between the exhaust emissions unit and the control unit during the OBD exhaust emissions test. In these cases the fuse (F6) of the MTA gearbox should be removed before the exhaust emissions test is started. Then the test procedure can be followed up to the step "start engine". The fuse must be replaced before the engine is started. After a brief wait of 20 seconds, the OBD exhaust emissions test can be continued.



Gear lever MTA gearbox



Fuse box engine compartment

# Bulletin

