# **Technical information**



## Product information BMW brake pads 8DB 355 012-321 / 8DB 355 015-601

### Changed brake pads

Due to a change in the serial equipment carried out by the vehicle manufacturer BMW, the following article allocation has been adapted as described in the following.

Brake pad 8DB 355 012-321 / T1596 will be replaced by brake pad 8DB 355 015-601 / T2029.

### Vehicle allocation


8DB 355 015-601 / T2029	E84, E89, E90, E91, E92,
	E93

Note:

Please observe the respective product allocations in the catalog.

#### **Mounting instructions**

The difference between both brake pads is the missing retaining spring (A) on the brake pad 8DB 355 015-601 / T2029 on the fist side. The missing retaining spring does not have any influence on the comfort conduct of the brake pad.



Page 1 of 1

2015

© Hella Pagid GmbH, Essen

Reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.

