

© Behr Hella Service GmbH, Schwäbisch Hall



Renault Safrane I (B54) *Model year: 1992 - 1996*

Problem with the air conditioning Engine does start/poor start

If there should be problems with the air conditioning with the above-mentioned vehicles and/or the engine doesn't start or has problems started, a faulty ground connection can be the cause.

The entry "compressor coupling" can be filed in the fault store. In this case, please check the ground strap and the attachment points in terms of corrosion and correct assembly. When replacing the ground strap please proceed as follows:

- Remove reinforcement sheet from under the engine
- Remove the ground strap from between the gear and bodywork and make sure that the screw and/or the thread in the gear do not become damaged
- Clean screw thread and attachment points
- Spray attachment points with suitable corrosion protection spray following replacement of the ground strap
- Remount reinforcement sheet

You will also find ground straps in Hella's electrics range.





1-1