Bulletin



© Behr Hella Service GmbH, Schwäbisch Hall 01. Oktober 2005 1-1

VW Golf 4

Pollen filter

The pollen filter, *Hella* N°.: 8FL 352 124-001 or 8FL 352 204-001 (with activate carbon filter), can be found under the water channel cover on the co-drivers side. To replace the filter, the rubber, four screws (pic. 1) and the cover A (pic.2) must be removed carefully. Following this the filter can be changed through the opening shaft (pic.3) and the reassembly can be carried out in reversed order.

Be careful when mounting the new filter. The cover B (pic.2) should not be lifted to much. Otherwise the windscreen can be damaged.



picture 1



picture 2 picture 3

Bulleti