Technical.bulletin

CSC018 2016

Different size Hydraulic connections

Part Number: 804526, 804544

For Vehicle: Dacia, Nissan, Renault applications

The Valeo 804526 and 804544 conforms to the OE design and uses the smaller hydraulic connection that fits to the hydraulic pipe. In some instances other aftermarket providers have developed a larger hydraulic connection and a hydraulic pipe that converts the technology away from the OE design.

Due to the possibility of an OE hydraulic pipe removal on a previous repair there are two repair variables when installing a new 804544 or 804526 (dependent on vehicle application).

- 1. The concentric slave cylinder removed from the vehicle has the same small hydraulic connection to that of the 804526 or 804544. In this instance the OE hydraulic pipe is still in place and the replacement can be performed with just the concentric slave cylinder.
- 2. A concentric slave cylinder is removed with a larger hydraulic connection and the hydraulic pipe on the vehicle has been converted. When fitting the Valeo CSC the vehicle must be converted back to the OE hydraulic pipe. This hydraulic pipe can be obtained through the main dealer.



Fig 1. Image displays an 804544 with a small hydraulic connection



www.valeoservice.co.uk Valeo Service (UK) Ltd, Heming Road, Washford, Redditch, Worcestershire, B98 0DZ Tel: 01527 838300 Fax: 01527 523732

