



# febi

# Tipp

## A complete solution for Ford Mondeo 1+2!



Due to a change of design of the anti roll bar mounting by the car manufacturer, problems occurred when fitting the stabilizer mounting (febi 27355). The former semi-circular design has now been changed to a flat design identical to the original part (see picture 3).

This means the mounting clamp must also be changed. The stabilizer mounts and clamps should always be replaced in pairs to ensure a professional level of servicing.

### Stabilizer mounting repair kit (with clamps) febi 27400

This repair kit contains stabilizer mounts with matching mounting clamps as well as the required high tensile mounting screws (10.9 grade).

So you have everything you need to fit stabilizer mounts quickly!



Ask your febi partner for febi spare parts!  
All parts are also available on [www.febi.com](http://www.febi.com).



febi no. 90852, as at 11/07, subject to alterations, errors and omissions excepted

## [www.febi.com](http://www.febi.com)

febi UK Limited | Bilstein House, Green Lane Industrial Park  
Featherstone | Pontefract | West Yorkshire WF7 6TA | Great Britain  
Fon +44 1977 699777 | Fax +44 1977 707333 | E-Mail [sales@febiuk.co.uk](mailto:sales@febiuk.co.uk)

bilstein group

