



Ford
Mondeo I
Model year: from 1993
Engine: Zetec
With automatic gearbox CD4E
With air-conditioning

Damaged coolant hose /
Loss of coolant

With the above-mentioned vehicles, a frayed coolant hose can lead to loss of coolant. The coolant hose from the recovery bottle to the lower radiator flange is routed very closely along the V-ribbed belt and can become frayed through this. In some cases this can lead to loss of coolant. Check the course of the hose within the context of maintenance work and particularly in the event of complaints related to loss of coolant. If this hose is already damaged it should be replaced. If necessary, use a cable tie to fix the hose to the air-conditioning pipe to ensure sufficient distance to the V-ribbed belt.

Bulletin