Bulletin



Ford Transit Connect Model year: 2011-6-1 - 2011-10-31

Poor wiper performance Loose wiper arms Wiper function failure

On the vehicles listed above, there may be instances where the wiper arms become loose from the wiper arm holders. This is usually caused by a loosened hinge pin that connects the wiper arm to the holder. A poor wiping pattern, due to low contact force, may be indicative of loose wiper arms.

The vehicle manufacturer has already addressed the problem and notified the owners of the affected vehicles. It must be assumed, however, that for a variety of reasons not all vehicles have been checked or repaired.

To correct this, the existing wiper arms should be exchanged for modified wiper arms.

© Hella KGaA Hueck & Co., Lippstadt



Reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, pictures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.

