



Bulletin

Opel Corsa D Engine code: Z10XEP, Z12XEP, Z14XEP, Z13DTJ Model year 2007–2011

Vibrations and noises on the front axle

If the above fault occurs, it may be associated with the OE brake linings in the front axle. These vibrations or noises mainly occur when a light braking force is applied in urban traffic.

In this case, the brake linings must be checked as part of the diagnostics process and replaced if necessary.

Note

The vehicle manufacturer supplies modified brake linings for brake disks measuring 257 x 22 mm in this case.

OE part number: 93169254

Hella Pagid reference part number: 8DB 355 012-831