



Renault Safrane I (B54) Engine: 3.0 Ltr. V6

Damaged refrigerant lines

In the case of the above vehicles with production numbers S 000 001 to 009 314, damage to the refrigerant lines can occur in the area of the exhaust manifold, due to the effects of heat. Lines which have already been damaged should be replaced. As a precaution, refrigerant lines in the area of the exhaust manifold must be wrapped with heat protection tubing (e.g. from the Hella air conditioning range) and be secured away from the manifold if possible.

Important note:

The production number is not the chassis number.

It can be found on the vehicle identification plate. On vehicles prior to production year 1996 the plate is oval and is located in the engine compartment. The production number is stated in the penultimate row of numbers. From 1996, the vehicle identification plate is square and is located on the B-pillar on the passenger side. The production number is stated in the first row, on the right.

Bulletin