



Volvo V70 Estate up to model year 2000

Bulb replacement in the upper part of the combination rear lamp.

To change the bulbs in the upper part of the combination rear lamp, the loudspeaker cover must be removed and the loudspeaker taken out. To do this, proceed as follows:

- Unclip the loudspeaker cover (Fig. 1).
- Pull out the two red stoppers (Fig. 2) of the loudspeaker attachment.
- Unhook the lower loudspeaker bracket hook and pull out the loudspeaker bracket downwards (Fig. 3).
- Unclip the bulb holder (Fig. 4).
- Replace bulb, check function
- Refit components in reverse order.



Fig. 1




Fig. 2



Fig. 3



Fig. 4