## **Bulletin**



© Behr Hella Service GmbH, Schwäbisch Hall 01. Oktober 2005 1-1

## VW Sharan Ford Galaxy Seat Alhambra

## Low pressure service connector

On the above-mentioned vehicles the low pressure service connector is fitted below the right headlight (pic. 1). To use the connection the right indicator lamp must be removed. A Torx-screw (pic.2) must be removed, then the indicator lamp can pulled out towards the front.



picture 1



picture 2

