

Blower motor 715235 continuously running

Part Number: 715235

For vehicle: Citroen Xsara Picasso models

The Valeo Service Technical department have had several claims stating that blower motor 715235 continuously runs at full load.

After investigating the issue Valeo technicians have identified that the blower motor itself is not at fault and the defect is with the regulator control unit.

If this occurs the blower motor will not need replacing, only the regulator control unit (OE reference 9 140 010 283)



Regulator control unit OE 9 140 010 283